

Future Technology Devices International Ltd. TN_135 FT200XD Errata Technical Note

Document Reference No.: FT_000637

Version 1.5

Issue Date: 2014-07-24

The intention of this errata technical note is to give a detailed description of known functional or electrical issues with the FTDI FT200XD devices.

The current revision of the FT200XD is revision D, released November 2012.

Future Technology Devices International Limited (FTDI)





TABLE OF CONTENTS

1	FT	200XD Revision	2
2	En	ata History Table – Functional Problems	3
	2.1	Errata History Table – Electrical and Timing Specification Deviations	
3	Fu	nctional Problems of FT200XD	
	3.1	Revision A	4
	3.1.	1 USB Data Transfer	4
	3.1.	2 USB 3.0 Hosts	5
	3.2	Revision B	6
	3.2.	1 USB Data Transfer	6
	3.2.	2 USB 3.0 Hosts	7
	3.3	Revision C	8
	3.3.	1 USB Data Transfer	8
	3.3.2	2 USB 3.0 Hosts	9
	3.4	Revision D	9
4	Ele	ectrical and Timing specification deviations of FT200XD	10
	4.1	Revision A	10
	4.2	Revision B	11
	4.2.	1 Internal 3V3 Regulator	11
	4.3	Revision C	12
	4.4	Revision D	13
5	FT	200XD Package Markings	14
6		ntact Information	
~	hhaii	dix C – Revision History	10



FT200XD Revision

FT200XD part numbers are listed in Table 1. The letter at the end of date code identifies the device revision.

The current revision of the FT200XD is revision D, released November 2012. At the time of releasing this Technical Note there are no known issues with this silicon revision.

Part Number	Package
FT200XD	10 pin DFN

Table 1 FT200XD Part Numbers

This errata technical note covers the revisions of FT200XD listed in **Table 2**.

Revision	Notes
А	First device revision. Never sold publicly.
В	Second device revision. Launched 28 February 2012
С	Third device version. Released 11 th June 2012
D	Forth device version. Released 6 th November 2012

Table 2 FT200XD Revisions



2 Errata History Table – Functional Problems

Functional Problem	Short description	Errata occurs in device revision
USB Data Transfer	Transfer of data over USB stops unexpectedly	A, B and C
USB 3.0 Hosts	USB 3.0 Host occasional interoperability	A, B and C

Table 3 Functional Errata

2.1 Errata History Table - Electrical and Timing Specification **Deviations.**

Deviations	Short description	Errata occurs in device revision
Fault with internal 3V3 regulator.	Device VCC is designed to operate between 3V3 and 5V however with this errata the supply should not be set below 4.3V for correct operation.	В
3V3OUT does not start with load	During enumeration when load is connected to 3V3OUT no output voltage is present	A, B, C and D

Table 4 Electrical and Timing Errata



Functional Problems of FT200XD

3.1 Revision A

3.1.1 USB Data Transfer

Introduction:

An issue has been identified where the transfer of data over USB stops unexpectedly.

Problem:

The device is put into suspend mode during a transfer of certain data patterns most notable with binary zeros. This can halt the data transfer in certain circumstances and will require the device to be reenumerated to recover.

NB. It is the presence of this data pattern on the USB bus regardless of whether the data is intended for the FT200XD or other devices (e.q. a broadcast) on the bus that forces the suspend state.

Workaround:

This issue can be avoided by utilising the keep awake function of the chip. This will disable the USB suspend function of the chip and is therefore an intermediate workaround until revision D silicon is released with a permanent fix.

NB. With the workaround the chip will never enter lower powered suspend. However the keep awake current will be approximately 3mA.

To enable the keep awake function in the EEPROM, one of the CBUS pins needs to be configured as Keep-Awake#. This pin then needs to be tied to ground on the PCB. The FT Prog utility can be used to configure the CBUS pin.

Package specific:

The effected packages are listed in Table 5.

Package	Applicable (Yes/No)
FT200XD	Y

Table 5



3.1.2 USB 3.0 Hosts

Introduction:

An issue has been identified where the FT200XD will not enumerate when connected to certain USB 3.0 Hosts. So far FTDI have identified **ONE** such host.

Problem:

Certain USB 3.0 Hosts exhibit reduced reset recovery times after a USB reset, which can at times be faster or close to the USB 2.0 specification limit. The USB 2.0 specification states a USB reset recovery time of 10ms and in general almost all hosts allocate a much longer period than this. The FT200XD device may not enumerate if the reset recovery time is reduced.

This issue has been seen on one USB 3.0 Host controller and has not been seen on a USB 2.0 Host controller or other USB 3.0 Host controllers.

Workaround:

Reconnect the device to a USB 2.0 host. This issue has been seen only on one particular USB 3.0 Host controllers.

Package specific:

The effected packages are listed in Table 6.

Package	Applicable (Yes/No)
FT200XD	Y

Table 6



3.2 Revision B

3.2.1 USB Data Transfer

Introduction:

An issue has been identified where the transfer of data over USB stops unexpectedly.

Problem:

The device is put into suspend mode during a transfer of certain data patterns most notable with binary zeros. This can halt the data transfer in certain circumstances and will require the device to be reenumerated to recover.

NB. It is the presence of this data pattern on the USB bus regardless of whether the data is intended for the FT200XD or other devices (e.g. a broadcast) on the bus that forces the suspend state .

Workaround:

This issue can be avoided by utilising the keep awake function of the chip. This will disable the USB suspend function of the chip and is therefore an intermediate workaround until revision D silicon is released with a permanent fix.

NB. With the work-aoround the chip will never enter lower powered suspend. However the keep awake current will be approximately 3mA.

To enable keep awake function in EEPROM, one of the CBUS pins needs to be configured as Keep-Awake#. This pin then needs to be tied to ground. The FT Prog utility can be used to configure the CBUS pin.

Package specific:

The effected packages are listed in Table 7.

Package	Applicable (Yes/No)
FT200XD	Υ

Table 7



3.2.2 USB 3.0 Hosts

Introduction:

An issue has been identified where the FT200XD will not enumerate when connected to certain USB 3.0 Hosts. So far FTDI have identified **ONE** such host.

Problem:

Certain USB 3.0 Hosts exhibit reduced reset recovery times after a USB reset, which can at times be faster or close to the USB 2.0 specification limit. The USB 2.0 specification states a USB reset recovery time of 10ms and in general almost all hosts allocate a much longer period than this. The FT200XD device may not enumerate if the reset recovery time is reduced.

This issue has been seen on one USB 3.0 Host controller and has not been seen on a USB 2.0 Host controller or other USB 3.0 Host controllers.

Workaround:

Reconnect the device to a USB 2.0 host. This issue has been seen only on one particular USB 3.0 Host controllers.

Package specific:

The effected packages are listed in Table 8.

Package	Applicable (Yes/No)
FT200XD	Y

Table 8





3.3 Revision C

3.3.1 USB Data Transfer

Introduction:

An issue has been identified where the transfer of data over USB stops unexpectedly.

Problem:

The device is put into suspend mode during a transfer of certain data patterns most notable with binary zeros. This can halt the data transfer in certain circumstances and will require the device to be reenumerated to recover.

NB. It is the presence of this data pattern on the USB bus regardless of whether the data is intended for the FT200XD or other devices (e.g. a broadcast) on the bus that forces the suspend state

Workaround:

This issue can be avoided by utilising the keep awake function of the chip. This will disable the USB suspend function of the chip and is therefore an intermediate workaround until revision D silicon is released with a permanent fix.

NB. With the workaround the chip will never enter lower powered suspend. However the keep awake current will be approximately 3mA.

To enable keep awake function in EEPROM, one of the CBUS pins needs to be configured as Keep-Awake#. This pin then needs to be tied to ground. The FT Prog utility can be used to configure the CBUS pin.

Package specific:

The effected packages are listed in Table 9.

Package	Applicable (Yes/No)
FT200XD	Y

Table 9





3.3.2 USB 3.0 Hosts

Introduction:

An issue has been identified where the FT200XD will not enumerate when connected to certain USB 3.0 Hosts. So far FTDI have identified **ONE** such host.

Problem:

Certain USB 3.0 Hosts exhibit reduced reset recovery times after a USB reset, which can at times be faster or close to the USB 2.0 specification limit. The USB 2.0 specification states a USB reset recovery time of 10ms and in general almost all hosts allocate a much longer period than this. The FT200XD device may not enumerate if the reset recovery time is reduced.

This issue has been seen on one USB 3.0 Host controller and has not been seen on a USB 2.0 Host controller or other USB 3.0 Host controllers.

Workaround:

Reconnect the device to a USB 2.0 host. This issue has been seen only on one particular USB 3.0 Host controllers.

Package specific:

The effected packages are listed in Table 10.

Package	Applicable (Yes/No)
FT200XD	Y

Table 10

3.4 Revision D

No known issues at revision D.





Clearance No.: FTDI# 281

4 Electrical and Timing specification deviations of FT200XD

4.1 Revision A

4.1.1 3V3OUT

Introduction:

The FT200XD has a 3V3OUT pin to allow users to power external circuits with 3.3 volts.

Problem:

During enumeration when a load is applied to the 3V3OUT pin, no output voltage is present.

Workaround:

The external circuitry must be powered off during enumeration of the FT200XD. A power Mosfet can be used in conjunction with the PWREN# pin. PWREN# is used to show enumeration has been successful and the external circuity can now be switched on.

Package specific:

The effected packages are listed in Table 11.

Package	Applicable (Yes/No)
FT200XD	Y

Table 11



4.2 Revision B

4.2.1 3V3OUT

Introduction:

The FT200XD has a 3V30UT pin to allow users to power external circuits with 3.3 volts.

Problem:

During enumeration when a load is applied to the 3V3OUT pin, no output voltage is present.

Workaround:

The external circuitry must be powered off during enumeration of the FT200XD. A power Mosfet can be used in conjunction with the PWREN# pin. PWREN# is used to show enumeration has been successful and the external circuity can now be switched on.

Package specific:

The effected packages are listed in Table 12.

Package	Applicable (Yes/No)
FT200XD	Y

Table 12

4.2.2 Internal 3V3 Regulator

Introduction:

The FT200XD uses an internal regulator to generate 3V3 from a 5V source (VCC). The source should be variable from 3V3 to 5V.

Problem:

The VCC supply to the regulator must not drop below 4.3V for the correct 3V3 regulated output to be produced.

Workaround:

VCC must not be supplied below 4.3V. This issue will be corrected at silicon revision C.

Package specific:

The effected packages are listed in Table 13.





Package	Applicable (Yes/No)
FT200XD	Υ

Table 13

4.3 Revision C

4.3.1 3V3OUT

Introduction:

The FT200XD has a 3V30UT pin to allow users to power external circuits with 3.3 volts.

Problem:

During enumeration when a load is applied to the 3V3OUT pin, no output voltage is present.

Workaround:

The external circuitry must be powered off during enumeration of the FT200XD. A power Mosfet can be used in conjunction with the PWREN# pin. PWREN# is used to show enumeration has been successful and the external circuity can now be switched on.


Package specific:

The effected packages are listed in Table 14.

Package	Applicable (Yes/No)
FT200XD	Y

Table 14







4.4 Revision D

4.4.1 3V3OUT

Introduction:

The FT200XD has a 3V3OUT pin to allow users to power external circuits with 3.3 volts.

Problem:

During enumeration when a load is applied to the 3V3OUT pin, no output voltage is present.

Workaround:


The external circuitry must be powered off during enumeration of the FT200XD. A power Mosfet can be used in conjunction with the PWREN# pin. PWREN# is used to show enumeration has been successful and the external circuity can now be switched on.

Package specific:

The effected packages are listed in Table 11.

Package	Applicable (Yes/No)
FT200XD	Y

Table 15





FT200XD Package Markings

FT200XD is available in a RoHS Compliant 10 pin DFN package. An example of the markings on the package is shown in Figure 5.1.




Figure 5-1 Package Markings - FT200XD



Version 1.5

Document Reference No.: FT_000637

Clearance No.: FTDI# 281



Contact Information

Head Office - Glasgow, UK

Unit 1, 2 Seaward Place, Centurion Business Park

Glasgow G41 1HH United Kingdom

Tel: +44 (0) 141 429 2777 Fax: +44 (0) 141 429 2758

sales1@ftdichip.com E-mail (Sales) E-mail (Support) support1@ftdichip.com E-mail (General Enquiries) admin1@ftdichip.com

Branch Office - Taipei, Taiwan

2F, No. 516, Sec. 1, NeiHu Road

Taipei 114 Taiwan , R.O.C.

Tel: +886 (0) 2 8797 1330 Fax: +886 (0) 2 8751 9737

E-mail (Sales) tw.sales1@ftdichip.com E-mail (Support) tw.support1@ftdichip.com E-mail (General Enquiries) tw.admin1@ftdichip.com

Branch Office - Oregon, USA

7130 Fir Loop,

Tigard, OR 97223-8160

USA

Tel: +1 (503) 547 0988 Fax: +1 (503) 547 0987

E-Mail (Sales) us.sales@ftdichip.com E-Mail (Support) us.support@ftdichip.com E-Mail (General Enquiries) us.admin@ftdichip.com

Branch Office - Shanghai, China

Room 1103, No. 666 West Huaihai Road,

Shanghai, 200052

China

Tel: +86 21 62351596 Fax: +86 21 62351595

E-mail (Sales) cn.sales@ftdichip.com E-mail (Support) cn.support@ftdichip.com E-mail (General Enquiries) cn.admin@ftdichip.com

Web Site

http://ftdichip.com

System and equipment manufacturers and designers are responsible to ensure that their systems, and any Future Technology Devices International Ltd (FTDI) devices incorporated in their systems, meet all applicable safety, regulatory and system-level performance requirements. All application-related information in this document (including application descriptions, suggested FTDI devices and other materials) is provided for reference only. While FTDI has taken care to assure it is accurate, this information is subject to customer confirmation, and FTDI disclaims all liability for system designs and for any applications assistance provided by FTDI. Use of FTDI devices in life support and/or safety applications is entirely at the user's risk, and the user agrees to defend, indemnify and hold harmless FTDI from any and all damages, claims, suits or expense resulting from such use. This document is subject to change without notice. No freedom to use patents or other intellectual property rights is implied by the publication of this document. Neither the whole nor any part of the information contained in, or the product described in this document, may be adapted or reproduced in any material or electronic form without the prior written consent of the copyright holder. Future Technology Devices International Ltd, Unit 1, 2 Seaward Place, Centurion Business Park, Glasgow G41 1HH, United Kingdom. Scotland Registered Company Number: SC136640

11/07/2012



Document Reference No.: FT_000637 Clearance No.: FTDI# 281



Appendix C - Revision History

TN_135 FT200XD Errata Technical Note Document Title:

Document Reference No.: FT_000637 Clearance No.: FTDI# 281

http://www.ftdichip.com/FT-X.htm Product Page:

Document Feedback: Send Feedback

Version 1.0 First Release 09/03/2012 Version 1.1 Added rev C and Updated China address 11/06/2012 Version 1.2 Added USB data transfer issue 11/07/2012

Version 1.3 Added USB 3.0 hosts and note to Problem section of USB data transfer

Version 1.4 Added revision D - no known issues,

10/06/2013 updated contact information

Version 1.5 Added