



PCN Tracking Number: PCN_FT_046

Issue Date: 2024-01-15

Product Change Notification

Rev 01

Product Part Number	FT4232HQ FT4232H-56Q FT4232HL	Estimated implementation date
Description of Change	1. Lead Frame 2. Packing Material	June 2019
Reason for Change	FT4232HQ: To improve the soldering pad to prevent the soldering issue. FT4232H-56Q: Tooling Change FT4232HL: Tooling Change	
Detailed Description	1. Produce new lead frame and package. 2. No functional or characteristic changes.	
Impact to Data sheet	1. Update FT4232H Datasheet for new lead frame description. 2. Update AN116 for packing description -Tape/Reel/Tray description.	
Benefit of Change	FT4232HQ: To improve the soldering pad to prevent the soldering issue.	
Markings to distinguish revised from:	Datecode from 1915-C	
Sample Availability	April 2019	
Risk Assessment, Fit Form and Function & reliability	No function impact, No reliability impact, Fit form compatible with an existing package.	
PDF Download	http://www.ftdichip.com/Support/Documents/ProductChangeNotifications/PCN_FT_046.pdf	
Others:	https://www.ftdichip.com/Support/Documents/DataSheets/ICs/DS_FT4232H.pdf https://www.ftdichip.com/Support/Documents/AppNotes/AN_116_FTDI%20Devices%20Tape%20and%20Reel%20Dimensions.pdf	
<p>For further information, please contact your local FTDI Representative.</p> <p>Note: Product number updated for better clarification.</p>		